

Filo

Recent (MPL (12/29/8/

July 31, 1981

Mr. William Guyette, President Advanced Circuitry Division Litton Industries Incorporated P.O. Box 2847 4811 W. Kearney Springfield, MO 65803

R00337264 RCRA RECORDS CENTER

Dear Mr. Guyette:

Enclosed is a copy of the inspection report conducted by the Missouri Department of Natural Resources on June 16, 1981. This letter will detail what is required of your company along with the deadline date for each requirement.

- Due to the contamination found in your monitoring wells and other ground and surface water samples near your facility (see enclosed report from the MoDNR Laboratory Services Program), the Missouri DNR, under the authority given it in Section 260.380.1(9) RSMo. request all previous analysis of your monitoring wells, sanitary lagoon, and percolation lagoon (lagoon A). Litton Industries, Inc. must also develop a monitoring plan to determine, to the satisfaction of the Department, that there is no longer any hazardous waste constituents in any waste stream which enters the lagoons, and then the ground water. This monitoring plan should include the necessary waste streams, the clarifier, the sanitary lagoon, and the percolation lagoon. As part of the plan include a sketch of the portion of the plant which includes these three processes and any incoming waste streams, sampling locations and methods to obtain representative samples, sample handling procedures (type of containers, preservative, if any, storage conditions, etc.), sampling frequency or time table, analysis perameters for each sample and the registered laboratory performing the analysis, and all previous analysis as requested above. This plan with all it's parts is to be submitted to the regional office and this office by September 1, 1981.
- 2. Achieve the required two foot freeboard in the percolation lagoon (A lagoon), and the treatment tank by September 18, 1981. Inform this office and the regional office by September 1, 1981, of the steps you plan to take to achieve the two foot free board.

DETERMINED NOT CONFIDENTIAL"

7/25/83

Division of Environmental Quality Robert J. Schreiber Jr., P.E. Director

Christopher S. Bond Governor Fred A. Lafser Director

Mr. Guyette Page 2 July 31, 1981

- 3. Install warning signs and develop adequate security measures to prevent the unknowing entry of persons or livestock into the percolation lagoon area (Unsatisfactory Features #3) by September 1, 1981. Inform this office and the Regional Office of the improved security at the percolation lagoon by September 1, 1981.
- 4. Immediately mark and label all containers of hazardous waste as described in Numbers 4 and 5 of the "Unsatisfactory Features".
- 5. "Unsatisfactory Features" Number 2 should be completed by September 1, 1981.
- 6. "Unsatisfactory Feature" Number 6 should be completed by October 9, 1981. The present closure plan lacked detail of the steps needed for, A) removal of the sludge and B) equipment decontamination. There must also be included with the closure plan a documentation to indicate your firm's financial assurance/mechanisms for the facilities surface impoundments closure. Please review the enclosed Subparts G and H of 40 CFR Part 265 from the January 12, 1981, Federal Register. Submit a copy of the revised closure plan and documentation of financial assurance to this office and the Regional Office by October 9, 1981.

Below is a summary of the compliance schedule which must be met by your company.

Immediately

-Mark and label all containers according to DOT

September 1, 1981

-Submit monitoring plan

-Submit proposed steps to achieve a two foot freeboard

-Improved security at percolation lagoon -Notification to MDNR of improved security -Contingency plan to appropriate authorities

September 18, 1981

-Two foot freeboard in percolation lagoon and treatment

tank

October 9, 1981

-Closure plan revised and submitted to MDNR

-Assurance of financial requirements

Mr. Guyette Page 3 July 31, 1981

If there are any questions concerning the requirements of this letter, please don't hesitate to contact either Art Groner or Paul Meiburger of this office, or Burt McCullough of the Springfield Regional Office.

Sincerety.

Ed Lightfoot

Deputy Director

Air and Land Branch

EL:PM/db

Enclosure

cc: David Doyle, EPA Enforcement

MODNR Water Pollution Control Program



Litton Systems, Inc.
Advanced Circuitry Division
4811 West Kearney
Springfield, Missouri 65807
(417) 862-0751
MDNR #01317
EPA I.D. #MODO07152903

On June 16, 1981 Burt McCullough, Art Groner, and Lyle Crocker of the Missouri Department of Natural Resources conducted a hazardous waste compliance inspection at Litton Systems, Inc.at Springfield in Greene County, Missouri.

Litton manufactures printed circuit boards. The manufacture of these boards consists of a copper plating process. Litton generates about 374,044 kg/year of hazardous waste as follows: chrome sulfuric acid (3,474 kg/year), waste oils (5,144 kg/year), electroplating wastewater treatment sludge (365,426 kg/year). Sludges are shipped to Bob's Home Service, waste oils are shipped by Radium Petroleum Company, and acids are shipped to National Industrial Environmental Services.

UNSATISFACTORY FEATURES:

- 1). Insufficient freeboard at hazardous waste percolation lagoon. (40 CFR 265.222)
- 2). Copies of contingency plan not circulated to appropriate state and local agencies. (40 CFR 265.53)
- 3). Inadequate security at waste handling facilities. (40 CFR 265.14)
- 4). Inadequate labeling of hazardous waste. (40 CFR 262.31)

5.

- 5). Inadequate marking of hazardous waste. (40 CFR 262.32)
- 6). Inadequate closure plan. (40 CFR Part 265 Subparts G and H)
- 7). Inadequate freeboard at waste treatment tank. (40 CFR 265.192)

COMMENTS:

The percolation lagoon had $4\frac{1}{2}$ inches of freeboard on the date of inspection. This lagoon contains about 8 million gallons of electroplating wastewater. This lagoon is adjacent to a sinkhole. Overflow of the lagoon or failure of the dikes would result in drainage to that sinkhole. About one foot of freeboard was observed on a waste treatment tank. This tank is used to mix a floculant with the wastewater prior to disposal in the percolation lagoon.

Although security guards are posted at the plant at all times, the fence surrounding the plant is inadequate to restrict entry. No sign with the legend "Danger - Unauthorized Personnel Keep Out" was posted at the gate.



Drums of hazardous waste at the shipping dock were not marked in accordance with D.O.T. regulations, or labeled in accordance with D.O.T. regulations. These drums also did not have the date of accumulation marked on the drum. Some of these drums, containing spent acids, were missing bungs. No type of containment was provided in the event of spillage from these drums.

The contingency plan developed pursuant to 40 CFR 265.51 adequately meets the requirements set up in the regulations. Copies of this plan, however, are not circulated to the agencies specified in the regulations.

Throughout the plant, there was a considerable amount of spillage on the floor, etc. Floor drains go to the percolation pond. Because of the diversity of materials used within the plant, it is impossible to know what types of materials are going into the percolation lagoon and ultimately ending up in the groundwater.

RECOMMENDATIONS:

- 1). Get 2 feet of freeboard on the percolation lagoon.
- 2). Get 2 feet of freeboard on the waste treatment tank.
- 3). Label and mark all containers of hazardous waste in accordance with D.O.T. regulations.
- 4). Post warning signs at access points to the plant.
- 5). Circulate the contingency plan to applicable agencies.
- 6). Improve closure plan to incorporate deficiencies.
- 7). Develop better housekeeping practices.

APPROVED:


John R. Nixon, P.E.

Administrator

SUBMITTED:

Burt McCullough

Environmental Specialist II



Report of Investigation Litton Advanced Circuitry Division May 20, 1981 JUN301921

SOLID WASTE MANAGEMENT PROGRAM

INTRODUCTION

At the request of the Water Pollution Control Program, an investigation was conducted of the Litton Advanced Circuitry Division in Springfield, Missouri, and various sites in the vicinity during the period from 1000 to 1800, May 20, 1981. The purpose of the investigation was to determine the source of volatile organics found in earlier analyses, and the effect on local ground water. Sampling was performed by David Paulsen and Larry Alderson of the Laboratory Services Program, DEQ. Personnel involved in the inspection included Jim Dow, Production Engineer with Litton, Bob Carson and Karen Chandler, with the City of Springfield, and Burt McCullough and John Nixon of the Springfield Regional Office.

METHODS

Grab samples were collected by filling appropriate containers while maintaining a zero head space to prevent the loss of volatile organics.

At the request of Litton representatives, two (2) extra sets of samples were collected for comparative analyses. Samples were collected at each of the following locations:

Sample Number

81-6227 - Fulbright Springs - included as a control.

81-6228 - Unnamed spring located on Stephens property feeding Clear Creek (this site was substituted for the upper end of Clear Creek at Clear Creek Park off Rt. AB - permission to enter the property was denied).

81-6229 - Ritter Spring #1 West

81-6230 - Ritter Spring #2 East

81-6231 - Fantastic Caverns - cave spring

81-6232 - Fantastic Caverns - potable water supply

81-6233 - Little Sac River - at Fantastic Caverns

81-6234 - Litton Sanitary Lagoon

Page Two
Litton Advanced Circuity Division
May 20, 1981
Tune 23, 1981

METHODS (CON'T)

Sample Number

81-6235 - Litton "C" Lagoon

81-6236 - Litton "A" Lagcon

81-6237 - Litton Monitoring Well - West

81-6238 - Litton Monitoring Well - East

Procedures used in the analyses were performed in accordance with those outlined in EPA Method Number 624. This method uses a purge and trap device in conjunction with a Gas Chromatograph/Mass Spectrometer.

OBSERVATIONS

Starting with Fulbright Springs, to be used mainly as a background sample, the investigation moved to Clear Creek Park off Route AB. The owner of the park insisted that no samples were to be collected on his property, so a small nameless spring on the Stephens property neighboring the park was substituted.

The Ritter Springs #1 West and #2 East, were visited next. Ritter Spring #1 West was particularly noted as having a much higher flow and was more turbid than was observed on a prior visit of February 25, 1981.

With the help of Russell Campbell, employee of Fantastic Caverns, samples were collected from a cave stream, the potable water supply, and the Little Sac River, which bordered the Fantastic Caverns property.

Litton's Sanitary Lagoon was sampled from a canoe using a Kemmerer sampler at a depth of about two (2) feet. Litton's "C" Lagoon had been pumped dry, but contained a small amount of water due to recent rains. The "A" Lagoon, which was noted to be very full, about one (1) foot from the top of the dike, was also sampled from a canoe using the Kemmerer sampler at a depth of about three (3) to four (4) feet.

The monitoring wells West and East, located just North of the "A" Lagoon, were sampled by using a small hand operated diaphragm pump supplied by Litton.

RESULTS

The results for the samples collected are attached to this report as Appendix A.

DISCUSSION

The two (2) monitoring wells were not bailed prior to sampling, therefore, some of the compounds found in those samples may have been due to leaching of the PVC casing from which the wells were constructed.

Chlorination of the potable water supply at Fantastic Caverns may also have contributed to the type of compounds found in that sample.

Submitted by

Larry Alderson

Environmental Specialist II

Date

June 23, 1981

Approved by

James H. Long, Director
Laboratory Services Program

cc: Richard Rankin, Director of Staff, Water Pollution Control Program
Art Groner, Environmental Specialist IV, Solid Waste Management Program
Burt McCullough, Environmental Specialist II, Springfield Regional Office
Robert Schreiber, Director, Division of Environmental Quality


/ds

"ENFORCEMENT SENSITIVE"

COMPOUND NAME		Litton Sanitary Lagoon	Litton C Lágoon	Litton A Lagoon	Litton Monitoring Well West	Litton Monitoring Well East
	13	81-6234	81-6235	81-6236	81-6237	81-6238
Trichloroethylene (ug/1)	1	233	*	*	106	30
1,2 Dichloropropane (ug/1)		, *	4.1	4.3	119	105
1,1,1-Trichloroethane (ug/1)	,	*	*	3.2	67.9	
Trans-1,2-Dichloroethylene (ug/1)		27.5	*	J.2 *		47.2
loroform (ug/1)		*	*		J	256
Fromodichloromethane (ug/1)		*		4.2	*	e ense Hartjø tals
Dibromochloromethane (ug/l)			*	*	*	r en
Vinyl Chloride		*	*	*	*	* * * * * * * * * * * * * * * * * * * *
1,1-Dichloroethylene (ug/1)		*	#	*	59.4	58.3
1,1-Dichloroethane (ug/1)	1	*	*	*	14.3	12.5
	- Table	*	*	*	112	132
Additional peaks found in some samples were identified using the NBS Lib	rary. A gross estimate of remoun	tration wa	s made.			
dibromomethane (ug/l)						
1-butene (ug/1)		*	*	*	*	*
thiobismethane (ug/l)		*	*	15	*	
2-propanone (ug/1)		*	* .	45	*	
		*	*	75	*	
carbon disulfide (ug/1)		*	*	35	*	
tetrahydrofuran (ug/1)		*	*	16	*	
1-butanol (ug/1)		*	*	300	*	

^{*}The compound was not found or it was less than 3.0 ug/l.

FENFORCEMENT SENST



e de en la compaña de la c En la compaña de la compaña	CKLIST FOR INSPECTION OF CLOSES	RO USE
	Name of Facility: Litton Systems Inc Advanced Circuitry div.	Inspection file
p. T.	Address: 4811 W. Kenney	No.
! ^	Springfiers, mo 65803	Reviewer
	EPA Generator ID Number: MODOO7152903 MONR-01317	Date reviewed:
	Facility Inspection Representative: James Dow	Form "A"
	Title: Frank Engineer Facilities Mar	
	Telephone Number: 417-862-0751.	· · · · · · · · · · · · · · · · · · ·
ert. Regs. 0 C.F.R. art:	1. Please provide a brief narrative explaining the type of work that occurs at the generator.	activity
	Manufacture of Printed Circuit Boards	
	2. Does the generator dispose of its wastes	
·	A. On-site (Circle one or both) B. Off-site	
÷	Note: if on-site, then checklist for both a generator and facility must be completed if on-site more than 90	TSD days.
Þ	3. What is the amount of hazardous waste (in kilograms) produce generator facility in a month? in a year? (If the amount is less than 1,000 kg/month, then the facility qualifies as a small generator and Form C should be complete of Form A.)	v
	4. What categories of hazardous wastes result from the generator facility? Please circle:	r's
į	A. Ignitable wastes	Yes No
	B. Reactive wastes	Yes No
	C. Corrosive wastes	Yes No
	D. EP Toxic wastes	Yes No
ţ	E. RCRA Listed Waste	

CKLIST FOR INSPECTION OF C

 \mathbf{U}

262,12

Is the generator presently...

Circle one

Treating hazardous waste?

Yes

Storing hazardous waste?

Yes

C. Disposing hazardous waste?

Yes

if the generator performs any of the activities noted in Question 5, then the inspector must complete Form B, entitled "RCRA Checklist for inspection of hazardous waste treatment, storage and disposal facilities."

No

No

No

Is a manifest system currently in operation at the generator's facility so that offsite shipment of hazardous wastes can be tracked?

Yes No

7. Please inspect the generator's manifest for the following information:

Ye.

Is the TSD facility which receives a generator's hazardous waste identified by name, address, and EPA ID number?

Is an alternative facility designated in case of an emergency?

Is a serialized manifest document number included on the form?

Is the generator's name, address, telephone number and EPA ID number included on the form?

No

No

No

Is the name and identification number of each transporter included on the form?

Is a description of the generator's hazardous waste to be treated, stored, or disposed included on the manifest?

Is the quantity of each waste by units of weight or volume Ġ. and the type and number of containers loaded in the transport vehicle included on the manifest form?

Ýes 110

Is the following certification noted on the generator's manifest form and is the certification acknowledged by

(Yes

the generator's signature? "This is to certify that the above-named materials are

properly classified, described, packaged, marked, and labeled and are in proper condition for transportation

No

No

according to the available regulations of the DOT and EPA." I. Are there adequate copies of the manifest available for generator, transporter, and TSD's?

8. Is hazardous waste being stored on-site by the generator for

Yes

Ifeso,

A. Is the date accumulation of waste began clearly marked on (3)each storage container?

,34(a)

2.22

262, 20

262.20(c)

62.20(a)

62.20(a)

(2)

(3)





		•	
262.3¼(a)(2	B. Are storage containers in good condition, i.e., no corrosion, leaking, or structural deformations?		
262.34(a)(4	S	Yes	oil Gil
	9. Does the generator have an established contingency plan to deal with emergencies that may impact hazardous waste currently in storage at the facility?	Yes) ио
?65.16(a)	10. Have facility personnel successfully completed a program of classroom training or on-the-job training in hazardous waste management procedures?	Yes	No
165.16(d)	11. Does the generator facility maintain a record of job titles for personnel that are involved with hazardous waste management and the name of the employee filling each job?	Yes	No
65.16(d)(2)	12. Does the generator facility have on record a written position description for each jcb title noted in Question #11?	Yes	No
55.16(d)(3)	13. Does the facility presently maintain a written description of the type and amount of introductory and continuing training for those employees noted in Question #11?	Yes	No
55.32(a)	14. *Does the generator facility have installed the following equipment:		•
	A. An internal communications or alarm system capable of providing immediate emergency instructions to facility personnel if the hazardous waste storage area is threatened by fire or explosion?	(e)	No
	B. A device at the scene of hazardous waste generator operations capable of summoning emergency assistance from Police, Fire departments, etc.?	<u>(Yes</u>	No
	C. Fire control equipment and an adequate supply of fire fighting water or fire supression chemicals?	Yes	No
5.35	15. *Does the generator facility have adequate aisle space to allow the unobstructed movement of personnel and equipment during emergencies?	Yes	No
15.50	16. Does the facility have a contingency plan which contains the following elements:		
5.52(c)	A. A detailed description of emergency procedures facility personnel will implement in response to fires, explosions, or unplanned releases of hazardous wastes to air, soil, and water?		M-
5.52(d)	B. A detailed description of arrangements formally agreed	(IE)	No
•	to by local police, fire departments, and State and local emergency teams to provide assistance during emergency situations?	Yes	
·		162	WO

		4
	•	
of the	Yes	No
four		
ry to	Yes	No
Management r their	Yes	No
encountered.		

265.52(d) C. A listing of names, addresses, and phone numbers generator facility emergency response coordinator Note: This listing should include names and phone nu of emergency coordinators available on twentyhour basis. 265.52(e) D. A list of appropriate emergency equipment necessar cope with emergencies at the generator facility? 165.52(f) E. *An evacuation plan for the generator facility if N believes such a plan is a definite requirement for particular generator facility. 17. Please provide detailed comments on specific problems during the inspection For instance, industry requests for clarification of specific RCRA rules and regulations and their applicability at the facility can be noted below or described in a separate memo attached to the inspector's checklist. Inspector's Name: BURT McCullough Title: Environmental Specialist Agency: Mo. Nept. Natural Resources Office location: Springfield Regional Office Date of Inspection: 6-16-81 Inspector's Name: Title: Office location: Date of Inspection:

	RCRA CHI S.ST FOR INSPECTION OF TSD FACILITIES	RO USE	
	Name of Facility: See p.	Inspection	
	Address:		riie
7		No.	
•	EPA TSD ID Number:	Reviewer	
		Date review	ed
	Facility Inspection Representative:	Form "B" .	
	Title:		
	Telephone:		
	SITE CHARACTERIZATION (Please denote if the facility present or disposes of hazardous waste. Also, priate sub-category that occurs at the facility.)	ly treats, s mark the ap particular	tores,
ř	TREATER		
	Filtration Open Pile	POSER Landfill ope	ration
	Recycling/Recovery	Land treatme Surface Impo	n t
	Chem/Phys/Bio TreatmentsBelow ground tank(s)	Incineration Other	didicalif
	Reprocessing Other Solvent Recovery	o cher	
	Other		
.1	INSPECTION PROCEDURE		
		<i>r</i>	
	1. Does the facility generate hazardous wastes?	Yes) No
	Note: Please complete the generator's checklist if TSD facility generates hazardous wastes which are disposed off-site.		, 110
.13(b)	2. Does the facility have in place a waste analysis plan?		
	If so,	Yes	No
13(a)	A. Does the plan enable facility personnel to identify haza wastes being handled by the facility?	rdous :	
13(c)	B. Does the plan enable facility personnel to confirm that wastes actually received at the TSD facility are the wast indicated on the generator's manifest form?	Yes	No
	3. *Does the TSD facility have a 24-hour surveillance system whice monitors and controls entry to the active portion of the faci	Yes th lity? Yes	No No
i		_	-

7 .	A. If not, does the facility have an artificial or natural boundary which surrounds active portions of the facility and,	Tes	No
	B. A means to control entry at all times, i.e., gates, attendants, locked entrances, etc.?	Yes	No
265.14 (c)	4. *Does the TSD facility have a restricted access sign posted at each entrance to the active portion of the facility? (An example would be: "Danger - Unauthorized Personnel Keep Out!"	Yes	(13)
·	If so,		Ŭ
	A. Is the sign legible from a distance of 25 feet?	Yes N.	V. No
	B. Is the sign in English or any other foreign language predominant to the geographical area?	Yes	· No
?65.15(d) ?65.15(b)	5. Does the TSD facility have an inspection log and a written schedule for inspecting all emergency equipment, security devices, and operating and structural equipment, important to the prevention, detection or response to environmental/human health emergencies?	Yes	No
265.16(a)	6. Have facility personnel successfully completed a program of classroom training or on-the-job training in hazardous waste management procedures?		No
?65,16(d)	7. Does the TSD facility maintain a record of job titles for personnel that are involved with hazardous waste management and the name of the employee filling each job?	Yes	No
!65.16(d)(2)	8. Does the TSD facility have on record a written position description for each job title noted in Question #6?	Tes .	No
:65.16(d)(3)	9. Does the facility presently maintain a written description of the type and amount of introductory and continuing training for those employees noted in Question #6?	Yes	No
65.32(a)	10. *Does the TSD facility have installed the following equipment:	•	
	A. An internal communications or alarm system capable of providing immediate emergency instructions to facility personnel if the hazardous waste storage area is threatened by fire or explosion?	Yes 1	10
	B. A device at the scene of hazardous waste TSD operations capable of summoning emergency assistance from Police, Fire departments, etc.?	· (Yes)	So.
	C. Fire control equipment and an adequate supply of fire fighting water or fire supression chemicals?		Io
65.35	<pre>11. *Does the TSD facility have adequate aisle space to allow the unobstructed movement of personnel and equipment during emergencies?</pre>	Yes K	0

•		•	
265,50	12. Does the facility have a contingency plan which contains the following elements:		·
265.52(c)	A. A detailed description of emergency procedures facility personnel will implement in response to fires, explosions, or unplanned releases of hazardous wastes to air, soil, and water?	K	.
265.52(d)	B. A detailed description of arrangements formally agreed to by local police, fire departments, and State and local emergency teams to provide assistance during emergency situations?	<u>(1)</u>	es No
:65.52(a)	C. A listing of names, addresses, and phone numbers of the TSD facility emergency response coordinators? Note: This listing should include names and phone numbers of emergency coordinators available on twenty-four hour basis.	Ye Yes	
65.52(e)	D. A list of appropriate emergency equipment necessary to cope with emergencies at the TSD facility?	.	•
55.52(f)	E. *An evacuation plan for the TSD facility if Management believes such a plan is a definite requirement for their particular TSD facility?	Yes	No
i5.55	13. Does the facility have at all times at least one employee either on-call or on the site who is responsible for coordinating all emergency response measures?	(Ps)	No
	If so, please complete below:	(Es)	No
	Name: James Dow Title: Facilities Mose		
£5.70	Telephone Number: 862-075/	٠	•
	4. Does the TSD facility have a written operating record which contains the following information:		
i5.73(b)(1)	A. A description and the quantity of each hazardous waste received and the method and date of treatment, storage or disposal?		• .
5.73(b)(2)	B. The location of each hazardous waste within the facility and the quantity at each location?	Yes	No
5.73(b)(3)	C. Detailed records and regults of waste analysis and treatability tests performed on wastes coming into the	Vei	No
5.73(b)(4)	D. Detailed operating summary reports and description of all emergency incidents that required the implementation of the facility contingency plan?	(es	No
i.73(b)(5)	E. Detailed records and results of inspections performed on facility emergency equipment, TSD systems, and hazardous	Yes	1

. 1		•	
265.73()	F. Detailed monitoring, testing, and analytical data to insure compliance with the regulations?		_
	15. Have the TSD facility operators initiated the preparation of written closure and post closure plans in order to meet the May 1981 target date for implementation of these requires		es No
265.71	16. Does the TSD facility receive hazardous waste from off-site	Y	es No
	If yes, are the following procedures implemented:	Ye	es 🔞
	A. Manifest copies are signed and dated		· ••
	E. A copy is given to the transporter	(Tes	\
	C. A copy is sent to the generator	(Yes	
	D. A copy is returned and filed at the TSD facility	Yes	
	Note: These requirements do not pertain to onsite facilities unless such facilities also receive hazardous wastes from off-site sources		
55.90	17. Has the owner or operator implemented a groundwater monitoring program if surface impoundments, landfills or land treatment technologies are utilized at the facility?	· .	
	Note: Plan not required until one year after effective date of regulations.	Yes	No
	18. The inspector should check for the following conditions at the TSD facility:		
	A. Open fires		
	B. Fumes or gases	Yes 	• 🔞
	C. Leaks or corrosion in containers or other storage structures	Yes	
	2. Leachate to receiving streams	Yes	*
	E. Malfunction of equipment	Yes	69
	F. Bulging drums	Yes	(6)
	G. Excessive heat generation from storage facilities, lagoons, storage piles, etc.	•	
		Yes	(No)

Inspector's Name: See P. 4 Title: Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency: Office location:	,	Please provide detailed comments on specific problems encountered during the TSD facility inspection. For instance, industry request for clarification of specific rules and regulations and their applicability at the facility can be noted below or described in a separate memo attached to the inspector's checklist.	:s -
Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency:	•		•
Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency:			
Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency:	-		
Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency:	-		4
Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency:	-		
Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency:			
Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency:	•		
Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency:	*****		
Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency:			
Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency:			
Title: Agency: Office location: Date of Inspection: Inspector's Name: Title: Agency:	Inspector's	Name: See O . I	-
Office location: Date of Inspection: Inspector's Name: Title: Agency: Office location:		See P. 4	
Office location: Date of Inspection: Inspector's Name: Title: Agency: Office location:	Agency:		
Inspector's Name: Title: Agency: Office location:		ion·	
Inspector's Name: Title: Agency: Office location:	Date of Insp	ection	
Agency: Office location:		TOTAL	
Title: Agency: Office location:	Inspector's 1	Name:	
Agency: Office location:	Title		•
Office location:	Ageness		
Date of Inspection:	Office location	on:	
	Date of Inspec	ction:	

3)

R.O. USE

Inspection file No:

RCRA Checklist for Surface Impoundments

,

(Subpart K Section 265,222 "General Operating Requirements"

		·
Name of Fac	ility: See pl	Reviewer:
Address:		NCVICWCI,
		Data D. C.
EPA Generat	or ID Number:	Date Reviewed:
Facility In	spection Representative:	
Title:		Form "K"
Telephone N	umber:	
	•	
use surtace	ns contained in this checklist apply to owners and operators of impoundments to treat, store, or dispose of hazardous waste, ex des otherwise.	facilities that cept as Part
Pert. Regs. 40 C.F.R. Part:		
65.222	1. Is 2 ft. of freeboard maintained in the surface impoundment	? Yes 🔊
65.223	2. Do all earthen dikes have protective covers (e.g., grass, shale or rock) to minimize wind and water erosion and to preserve dike structural integrity?	Ces ::0
65.225(a) (1) & (2)	3. Are waste analyses conducted or written documentation obtain before placing a substantially different hazardous waste in a surface impoundment used for storage or treatment?	ned to Yes V.A.
55.226(a) (1)	4. Is the freeboard level inspected at least once each operation day?	ng Yes No
55.226(a) (2)	5. Is the surface impoundment, including dikes and vegetation, inspected once per week to detect leaks or deterioration or failures in the impoundment?	Veg No
•	6. Are the results of these inspections recorded in an inspection or summary?	on Yes No
55.229(a)	7. Are ignitable or reactive wastes stored in a surface impoundment: If so,	Yes No
55.229(a) (1)	a) Is the waste treated, rendered, or mixed before or immediately after placement in the impoundment so that the resulting waste, mixture or dissolution of material no longer meets the definition of ignitable or reactive waste under parts 261.21 or 261.23 of the RCRA regulation	ons? Yes No



265.230

b) Are incompatible wastes segregated in separate surface impoundments so that spontaneous reactions are avoided?

	_	_	
P	Ÿ	es.	
`	-	~	

No

inspector's name.	see P	4			
Title:		·	•		
Agency:				•	
Office location:					
Date of Inspection:					
•			•		
Inspector's Name:					
Title:			<u>.</u>		
Agency:					
Office location:					
Date of Inspection:					

- + S.		
ile	No:	
l :		

RCRA Checklist f	or Chemical,	Physical and	Biological	Freatment

(Subpart O Par	r 265 40 - 40	ananal Osasa	n .	

- , <u>R</u> t	SKA Checklist for Chemical, Physical and Biological Freatment	R.O. USE	
•	(Subpart Q Part 265,40 - "General Operating Requirements"	Inspection	file %
Y		r om p and a zon.	1110 110
	acility: See P.	Reviewer:	
Address:		Reviewel.	
FP1 Conou.		Date Reviewe	
	ator ID Number:		· .
	Inspection Representative:		-
Title:		Form "Q"	
Telephone	Number:		
	ions contained in this checklist apply to owners and operators of fardous wastes by chemical, physical, or biological methods in other appoundments and land treatment facilities except as Section 265.1 p		
Pert. Regs. 40 C.F.R. Part:			
265.401(b)	1. Are all treatment processes or equipment in good condition, i.e., not showing signs of leakage, corrosion or any other deterioration?	Yes	
265.401(c)	2. Are treatment processes or equipment with continuous inflow of hazardous waste equipped with a means to stop this inflow (e.g., waste feed cutoff system or bypass system to a standby containment device)		No.
165,402(1) & (2)	3. Are waste analyses performed or written documentation obtained before placing a substantially different hazardous waste into treatment processes or equipment?	ed Yes	No
	4. Is this information recorded in the facility's operating reco	ord? Yes	No
65.403(a) (1)	5. Are daily inspections conducted for discharge control equipme (e.g., bypass systems, waste feed cut-off systems, drainage systems and pressure relief systems)?	nt Yes	N _O
55.403(a) (2)	6. Is data gathered from monitoring equipment (e.g., pressure an temperature gauges) at least once each operating day?	d (es)	No
55.403(a) (3)	7. Are construction materials of the treatment process or equipm and immediate surrounding area inspected weekly for signs of	ent	

leakage, corrosion or any other deterioration?

	8. Are the results of these inspections recorded in an inspection log or summary?	Yes No
•	9. Are ignitable or reactive wastes placed in a treatment process? If so,	Yes No
265.405(a) (1)	A. Are the wastes treated, rendered, or mixed before or immediately after placement in the treatment process or equipment so that the resulting waste, mixture, or dissolution of material no longer meets the definition of ignitable or reactive wastes under Section 261.21 or 261.23 of the RCRA regulations?	بر Yes No
265.405(a) (1)	B. Are the wastes treated in such a way that they are protected from any material or conditions which may cause the waste to ignite or react?	Tes No
	10. Are incompatible wastes kept from being placed in the same treatment process or equipment?	No. A.
	Inspector's Name:See P. 4	
	Title:	
	Agency:	 :
**************************************	Office Location:	
	Date of Inspection:	
		•
	Inspector's Name:	
•	Title:	
	Agency:	

Office Location:

Date of Inspection:

•	part 1 Section 265.170 - "General Operating Requirements"	Inspect	ion fil	e No:
Name of Faci	lity: See P.	Reviewe	r:	
-		Date Re	viewed:	
EPA Generato	or ID Number:			
Facility Ins	spection Representative:	Form "	'I''	
Title:				
Telephone Nu	ımber:			
The question facilities t	s contained in this checklist apply to owners and operators of a hat store containers of hazardous waste, except as Section 265.1	ll hazar provide	dous wa	iste rwise.
Pert. Regs. 40 C.F.R. Part:				
65.171	1. Are all containers in good condition, i.e., not showing sign of leakage or corrosion or any other deterioration/deformat	ns ion?	ES	No
65.171	2. Are containers lined or made of materials compatible with hazardous wastes placed into them so that the container will not react or corrode with the hazardous wastes?	11	(es)	(1.0)
65.173(a)	3. Are all containers holding hazardous waste kept closed duri storage?	ing	Yes	6
65.174	4. Are areas where hazardous waste containers are stored inspending by the owner/operator at least once a week?	ected	Yes	No
65.15(d) 65.15(b)	5. Is an inspection log maintained? (See question #5 of TSD checklist.)		Yes	
65.176	6. Are containers holding ignitable or reactive waste located at least 50 ft. from the facility's property line?		(es)	. No
65.177(a)	7. Are incompatible wastes placed in the same container? (See Appendix 5 for examples.)	e	Yes	(%)

Are storage containers holding hazardous wastes which are

or other devices?

incompatible with nearby materials stored in containers, tanks, piles, or surface impoundments separated by dikes, berms, walls,

Yes

55.177(c)

Inspector's Name: See	p. 4		
Title:			
Agency			
Office location:			
Date of Inspection:			
Inspector's Name:			
Title:			
Agency:			-
Office location:			
ate of Inspection:			
		-	 -

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
Selember 1 percent	meritat for Tanks	
1723/2018 of 1000 Prop. 265.10	92 - "General Operating	Requirements"
		e marie sum analis dia liang

Name of Facility: See p

Address:

<u>")</u>	R.O. USE Inspection file No:
,	Reviewer:
	Date Reviewed:
	Form "J"
s of fa des oth	cilities that use erwise.

		-
EPA Gene	rator ID Number:	Date Reviewed:
Facility	Inspection Representative:	
Title:		Form "j"
Telephone	Number:	J
The questi	ions contained in this checklist apply to owners and operators of f. reat or store hazardous waste, except as Section 265.1 provides of	ncilities that upe
ert. Regs 0 C.F.R.		
65.17(b)	1. Are all tanks in good condition, i.e., not showing signs of leakage, corrosion, or any other deterioration?	
65.192(c)	2. Are uncovered tanks operated to ensure a minimum of 2 ft.	(igs) in
55.192(c)	3. If not, is the tank equipped with a containment structure (e.g., dike or trench), a drainage control system, or a diversion structure (e.g., standby tank) with a capacity that equals or exceeds the volume of top 2 ft. of the tank?	Yes 📆
5.192(d)	4. Are tanks with continuous inflow of hazardous wastes equipped with a means to stop this inflow (e.g., waste feed cut-off system or by-pass to a standby tank)?	
5,193(a) (1) & (2)	5. Are waste analyses conducted or written documentation obtained before placing a substantially different hazardous waste into a tank used for storage or treatment?	
(1)	6. Are daily inspections conducted for discharge control equipmen (e.g., by-pass systems, waste feed cutoff systems and drainage systems)?	
.194(a) (2)	7. Is data gathered from monitoring equipment (e.g., pressure and temperature gauges) at least once each operating day?	Yes (No)
.194(a) (3)	8. Is the level of waste in the tank checked at least once each operating day?	
		Ges No

265.194(a) * (4)	9. Is (are) the tank (or tanks) inspected weekly to detect corresion or leaking of fixtures or seams?		
	10. Are the results of these inspections recorded in an inspection log or summary?	Yes	
265,198	11. Are ignitable or reactive wastes stored in tanks? If so,	Yes	(سيلا)
265.198(a) (1)	a) Is the waste treated, rendered, or mixed before or immediately after placement in the tank so that the resulting waste, mixture, or dissolution of materials no longer meets the definition of ignitable or reactive wastes under Parts 261.21 or 261.23 of the RCRA Regs?	Yes	
(2)	b) Is the waste stored or treated in such a way that it is protected from any material or conditions which may cause the waste to ignite or react?	Yes	
65.198(b)	c) Is the owner/operator of a facility which treats or stores ignitable or reactive wastes in covered tanks in compliance with the National Fire Protection Association's (NEPA's) buffer zone requirements for tanks contained in tables 2-1 through 2-6 of the "Flammable and Combustible Code • 1977":	Yes (
	•	Ters	

and the same and t
•



P. O. Box 2847, Commercial Station, Springfield, Mo. 65803 417 862-0751

August 24, 1981

Mr. Ed Lightfoot
Deputy Director
Air and Land Branch
Missouri Department of Natural Resources
P. O. Box 1368
1915 Southridge Drive
Jefferson City, Missouri 66102

RE: Letter of July 31, 1981, directed to Mr. W. C. Guyette, President, Litton Advanced Circuitry Division

Dear Mr. Lightfoot:

On August 17, 1981, we met with local DNR officials, Ed Sears and Burt McCullough, to discuss the results of our RCRA inspection and your other requests. Our response to your letter is as follows:

Previous analysis of monitoring wells of sanitary lagoon and percolation lagoon: ACD files for the above were made available to Mr. Ed Sears and Mr. Burt McCullough for examination. After examination, Mr. McCullough was given copies of the files he requested.


Labeling of waste containers: The labeling of waste containers has been in compliance with D.O.T. regulations 49 CFR Para. 172. It is our opinion that barrels addressed in the unsatisfactory remarks were rinsed, empty, and awaiting return for deposit. All barrels addressed in the receiving area were either incoming material, or empty barrels, thus requiring no RCRA labeling. Please be advised that chemicals that could possibly constitute a spill problem will be moved into containment areas or inside the warehouse.

Monitoring Plan: After discussion of the monitoring plan with Mr. Ed Sears and Mr. Burt McCullough, we propose to monitor for Trichlorethylene. The plan includes a monthly sampling for three months, starting September 1, 1981, then quarterly thereafter, if a pattern has been defined. The samples will be of a grab type taken where indicated below. Samples will immediately be analyzed by our lab, or preserved on ice and shipped to Stewart Labs. The process for taking the samples is described below:

Mr. Ed Lightfoot August 24, 1981 Page 2

Effluent Flow and Grab Sample Points

x = sample point



Litton has purchased a new Gas Chromatograph to test for Volatile Organics. We expect to have it operational October 1, 1981. Until such time that it is operational, samples will be sent to Stewart Laboratories, Knoxville, Tennessee.

Treatment tank freeboard: The two foot freeboard required was achieved June 17, 1981, by an operational change which lowered the level of the treatment tank.

Percolation lagoon freeboard: The two foot freeboard required for the percolation lagoon cannot be practically met by September 18, 1981. As of August 24, 1981 the freeboard is 18-3/4". We request an extension to have a 24" minimum by January 30, 1982.

Security for the percolation lagoon: Security at the percolation lagoon will be achieved by installing a 3-strand barbed fence with a locked gate, around the base of the lagoon. Signs stating "Danger-Unauthorized Personnel Keep Out" will be posted at the gate and on each side of the fence as required. This will be completed by September 1, 1981.

Contingency Plan: The contingency plan will be distributed to local Fire, Sheriff, Police, City Sanitary Services, and DNR offices by September 1, 1981.

Mr. Ed Lightfoot August 24, 1981 Page 3

Closure Plan: New changes in the laws have required additional detail in the closure plans. The new plan is as follows:

On or about January, 1982, the city sewer system will be available for hook-up and Litton will begin use for effluent discharge. At this time, Litton will discontinue discharging effluent waters to A-pond and it will be allowed to percolate to zero level leaving a sludge on the base. At the present percolation rate, allowing for rain, and assuming a drop in the head pressure with the level, percolation will continue for approximately 300 days. This would put the start of disposal at about November 1, 1982.

Based on calculations approximately 1600 cu.yds. of sludge will have accumulated and will be removed to a hazardous waste site. This material will be removed with heavy equipment into 15 cu. yd. containers and permitted for shipment to Bob's Home Service in Wright City or National Industrial Environmental Services in Wichita, Kansas.

Decontamination of equipment will include washdown within the pond itself and dewatering of waste through our filter press. This material will also be shipped via our normal process to the landfill.

Actual closure will start in November and take approximately two months of excavation and loading time. Final closure will consist of grading over and seeding of the site.

In lieu of the above, ACD is investigating methods for rendering the sludge non-hazardous. In the event ACD is successful, we would submit a modified closure plan.

The Financial Assurance for closure is being addressed and will be completed by October 13, 1981.

If you have any questions or comments, do not hesitate to contact us.


Sincerely,

James K. Dow, P.E. Facilities Manager

c: John Nixon

Administrator, DNR Springfield Office

DEQ-4 7-75



(generator File

TELEPHONE OR CONFERENCE RECORD

File Litton Advanced Circuitry - Springfield	Date_	September 15, 1981			
TELEPHONE		CONFERENCE			
Incoming ()		Field ()			
Outgoing (X)		Office ()			
SUBJECT Financial Requirements for Closure of Pe	rcolation Lagoon	<i></i>			
PERSONS INVOLVED					
. Name	Representing				
Gerald P. Lucey	Legal Counsel, Litton Industries				
, Paul Meiburger	Missouri Department	of Natural Resources			
SUMMARY OF CONVERSATION Mr. Lucey briefly discusse	ed the content of his	September 14, 1981			
letter. I told him that Missouri Department of A					
over Federal EPA regulations, since we adopted in	and the second s				
265. Look for the Federal Register with standard					
released, and that is what is required by October					
13, 1981 date, so will the state. There is a pro	blem with Litton supp	oling their own			
financial requirements by means of their net wort					
MENNYMENTER entity in Missouri. Litton Systems i					
and Litton Systems alone does not have sufficient					
requirements.					
FINAL RESULTS					

Paul Meiburger

Signature

Contact

Gerald Lucy
Litton haductive;

4825 Scott: Suite 410


Schiller Park Illinous 60176

(312) 671-2930

Mr. Ott Flt

Marshall Mc Clemen hasurance CoLaw Angelo, Calif.

DEQ~4 1



TELEPHONE OR CONFERENCE RECORD

File Litton Industries - Springfield	Date September 23, 1981		
TELEPHONE	CONFERENCE		
Incoming ()	Field ()		
Outgoing (X)	Office ()		
SUBJECT Financial Requirements for Percol	ation Lagoon		
PERSONS INVOLVED			
Name	Representing		
W. C. Guyette	President, Litton Advanced Circuitry		
Paul Meiburger	Missouri Department of Natural Resources		
SUMMARY OF CONVERSATION After calling EPA i	n Washington, D.C., I found out that sometime		
next week a Federal Register will be coming			
	l to April 13, 1982. This will also postpone		
the State Requirements mentioned in previou			
Natural Resources and Litton: i.e., July 3			
September 10, 1981, James Dow from Lightfoo	•		
ACTION TAKEN			
FINAL RESULTS			
INAL RESULIS			
	· · · · · · · · · · · · · · · · · · ·		

cc: Ed Lightfoot

Paul Meiburger

Signature

4825 Scott Street, Schiller Park, Illinois 60176

651490 (Attn: LSPW)

910-4941231 (Attn: LSPW)

Telephone: 312 671-2930

Telex:

TWX:

LITTON INDUSTRIES

Law Department

September 14, 1981

Missouri Department of Natural Resources P. O. Box 1368
1915 Southridge Drive
Jefferson City, Missouri 65102
ATTN: Mr. Ed Lightfoot

RE: Advanced Circuitry Division, Litton Systems, Inc.

4811 West Kearney Springfield, Missouri

Dear Mr. Lightfoot:

This letter is intended to confirm our telephone conversation of September 9, 1981, wherein I advised you that I represent the Advanced Circuitry Division, Litton Systems, Inc. In your letter dated July 31, 1981, you established October 9, 1981 as the date for compliance with the financial responsibility requirements for closure. As I explained, Litton's Insurance Department in conjunction with Marsh & McLennon have been unable to locate a surety company that is willing to write a bond to satisfy these financial responsibility requirements. If you are able to provide me with the name of any surety companies writing these bonds, this information will be most helpful.

Assuming we are unable to locate a surety company, it would be appreciated if your office would consider granting Advanced Circuitry a waiver or variance from the financial responsibility requirements. Advanced Circuitry will discontinue the use of its sanitary and wastewater lagoons as soon as it can commence using the Municipal Sewer System. The extension of the Municipal Sewer System should be completed within the next few months and the System should be operative in January, 1982. Since the closure of these lagoons will commence in the foreseeable future, I hope it will be possible for the Department of Natural Resources to grant Advanced Circuitry either a waiver or a variance.

Very truly yours,

LITTON SYSTEMS, INC.

Gerald P. Lucey Legal Counsel

GPL/cs

cc: M. Doram

R. Enos

D. Miller

P. Meiburger

RECEIVED

SEP 1 7 1981

SOLID WASTE MANAGEMENT PROGRAM



September 10, 1981

Mr. James K. Dow, P. E. Facilities Manager Advanced Circuitry Division Litton Industries Incorporated P. O. Box 2847 4811 West Kearney Springfield, MO 65803

RE: Response to Your Letter of August 24, 1981

Dear Mr. Dow:

All of your actions in response to my letter of July 31, 1981, have met the approval of the Solid Waste Management Program except the following:

- 1. The proposed monitoring plan should also include sampling and analysis of the east and west monitoring wells. These wells should be pumped, and then allowed to recharge before the samples are obtained. The frequency of sampling and analysis for the monitoring wells and those points noted in your proposed plan should be monthly until February 1, 1982, at which point the Missouri Department of Natural Resources will receive the findings to determine if quarterly monitoring would be adequate till closure.
- 2. The freeboard on the percolation lagoon must be twenty four (24) inches. We will allow an extension of the original compliance schedule to a final date of October 30, 1981, for the necessary two feet of freeboard on the percolation lagoon.
- 3. Concerning the financial requirements for closure, personnel from the Solid Waste Management Program were in contact with Mr. Ott Elt of Marshall McClennen Insurance Company in Los Angeles, California, about the financial assurance mechanism for closure. There is a Federal Register which should be published in the very near future which will contain various options for assuring proper financial requirements for closure (40 CFR, Part 265, Subpart H). Litton Industries must meet one of these options by October 13, 1981.

Mr. James K. Dow, P.E. Page Two September 10, 1981


If there are any questions concerning this letter don't hesitate to contact Art Groner of the Solid Waste Management Program or Burt McCullough of the Springfield Regional Office.

Sincerely,

Ed Lightfoot Deputy Director Air & Land Branch

EL/PM/bki

cc: Water Pollution Control Program
Solid Waste Management Program
Springfield Regional Office
Gerald Lucey



MEMORANDUM

Date:

November 19, 1981

To:

Litton File, Greene County

From:

Burt McCullough

Subject:

Reinspection

1997

GRAM

On November 18, 1981, I reinspected Litton Industries at in Springfield. The initial inspection was performed on Ju During the June 16 inspection, the following unsatisfactory noted:

1. Insufficient freeboard on the lagoon.

2. Insufficient freeboard on the holding tank.

3. Inadequate labeling and marking of hazardous waste containers.

4. Accumulation date not marked on containers.

Inadequate security at facility.

Inadequate circulation of contingency plan.

All of the unsatisfactory features, with the exception of the lagoon freeboard, had been corrected. At the time of inspection, there was 12.25 inches of freeboard on the lagoon. This is a 272% over the earlier inspection results. In order to improve the freeboard level, Litton constructed higher berms on the lagoon. This lagoon will begin steps toward closure on January 1, 1982. For this reason, I do not recommend enforcement actions based on the improvements thus far and the length of time till closure.

Aside from the freeboard, which should correct itself by January 1, 1982, Litton appeared to be in compliance with RCRA.

cc Mr. Paul Meiburger, WMP

MC

Frank Dolan

IX. DESCRIPTION OF HAZARDOUS WASTES

Please go to the reverse of this form and provide the requested information.

î.				w	- 53 14 11
IX. DESCRIPTION OF I	IAZARDOUS WAST	ES (continued from f	ront)		
A. HAZARDOUS WASTES waste from non-specific				n 40 CFR Part 261.31 fo	r each listed hazardous
1	2	3	4	5	6
F 0 0 1	F 0 0 6	F 0 0 7	F 0 0 8	F 0 0 9	D 0 0 7
7	8	9	10	11	12
				26	23
B. HAZARDOUS WASTES specific industrial sources				R Part 261,32 for each	listed hazardous waste from
13	14	15	16	17	18
23 - 26	23 - 26	23 26	23 - 26	23 - 25	23 - 26
23 - 26	23 26	23 - 26	23 - 26	23 - 26	30
23 - 26	23 - 26	23 - 26	23 - 26	23 - 26	23 - 26
C. COMMERCIAL CHEMIC stance your installation h					33 for each chemical sub-
31	32	33	34	35	36
23 - 26	23 - 26	23 . 26	23 - 26	23 - 26	23 - 26
37	38	39	40	41	42
23 - 26	23 - 26	23 26	23 - 26	23 - 26	23 - 26
43	44	45	46	47	48
			23 - 26		23 - 26
D. LISTED INFECTIOUS W			CFR Part 261.34 for ea		
49	50	51	52	53	54
E. CHARACTERISTICS OF hazardous wastes your ins				esponding to the characte	eristics of non-listed
1. IGNITAE	· ·	2. CORROSIVE		CTIVE	□ 4. TOXIC
(DOO1)	(DC	002)	(D003)	1111 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	(D000)
X. CERTIFICATION I certify under penalty	of law that I have	personally examined	and am familiar wit	th the information su	hmitted in this and all
attached documents, ar I believe that the subm mitting false informatio	nd that based on my itted information is	inquiry of those ind true, accurate, and co	ividuals immediately omplete. I am aware	v responsible for obta	ining the information.
SIGNATURE		NAME & OFF	ICIAL TITLE (type or	print)	DATE SIGNED
1 XOMINDO	,	James K.	Dow, Faciliti	es Manager	11/7/80

I.D. - FOR OFFICIAL USE ONLY

EPA Form 8700-12 (6-80) REVERSE

EPA Form 8700-12 (6-80)

CONTINUE ON REVERSE

A American	***			WMODOO	7/52903	1
IX. DESCRIPTION OF H	AZARDOUS WAS	TES (continued from	front)	1 2	93 14	15
A. HAZARDOUS WASTES F waste from non—specific s	FROM NON—SPECIFIC cources your installation	C SOURCES. Enter the n handles. Use additional	four—digit number from al sheets if necessary.	n 40 CFR Part 261.31 f	or each listed hazardous	
F 0 0 6	F 0 0 7	F 0 0 8	F 0 0 9	23 - 26	23 - 26	A
B. HAZARDOUS WASTES F specific industrial sources y	ROM SPECIFIC SOUP	RCES. Enter the four-of	igit number from 40 CF	23 - 26	23 - 26	DETACH
specific industrial sources y	our installation handle	To the controller streets	in necessary.	n rart 201.32 for each	listed hazardous waste from	T
23 - 26	23 - 25	23 - 26	23 - 26	23 - 26	18	
23 - 26	20	21	22	23 - 26	24	
25	26	27	28	29	30	
C. COMMERCIAL CHEMICA stance your installation har	L PRODUCT HAZAR ndles which may be a h	DOUS WASTES. Enter azardous waste. Use add	the four—digit number of ditional sheets if necessary	from 40 CFR Part 261.3	33 for each chemical sub-	
	3.6	33	34	35	36	SECONOCIONAL
23 - 26	38	23 - 26	23 - 26	23 - 26	23 - 26	
23 - 26	23 - 26	23 - 26	23 - 26	23 - 26	23 - 26	
D. LISTED INFECTIOUS WA	STES. Enter the four-	-digit number from 40.0	23 - 26	23 - 26	23 - 26	The second secon
hospitals, medical and resea	rch laboratories your i	nstallation handles. Use	additional sneets if nece	essary.	from hospitals, veterinary	
23 - 25	23 - 26	23 - 26	52	53	5.4	SECOLO CONTRACTO DO CONTRACTO DE
E. CHARACTERISTICS OF N hazardous wastes your insta	ION-LISTED HAZAR llation handles. (See 4	DOUS WASTES. Mark O CFR Parts 261.21 — 2	"X" in the boxes corres 61.24.)	ponding to the characte	ristics of non-listed	Selection and a selection of the selecti
(D001)	E (D0	2. CORROSIVE	3. REACT		4. TOXIC (D000)	P) Sales of the sa
C. CERTIFICATION			A Participant and the	And the state of t	e king on the second	AD
I certify under penalty of attached documents, and I believe that the submitt mitting false information,	ed information is t	inquiry of those indi-	viduals immediately	mannamoible for abou	induced to the contract of the	ETACHA
GRATURE	1002		CIAL TITLE (type or pr		DATE SIGNED	
PA Form 8700-12 (6-80) RE	VERSE	19THES TOM	, Facilities N	lanager	6/20/80	noncold tomords

DETERMINED NOT CONFIDENTIAL"

7/25/83

- FOR OFFICIAL USE ONLY